


INTRODUCING:

Repair Kits & Components for Alcatel ADP/ADS/RSV Dry Pumps & Boosters

Engineered to exacting standards and designed part for part to ensure optimum pump performance.

Contact Us: [+1 \(716\) 297-2039](tel:+17162972039)
info@precisionplus.com

Buy Online: www.precisionplus.com



Pump & Booster Repair Kits

Kit contents available online.

ADP122L Dry Pump Repair Kit
Part Number: [110910](#)

ADP122P Dry Pump Repair Kit
Part Number: [110911](#)

RSV602 Booster Repair Kit
Part Number: [106927](#)

ADS602L Dry Pump & Booster Repair Kit
Part Number: [ADS602L](#)

ADS602P Dry Pump & Booster Repair Kit
Part Number: [ADS602P](#)

STATORS

HP Stator
Part Number: [110931](#)
MODELS: ADP122

LP Stator
Part Number: [110932](#)
MODELS: ADP122

LP1 Stator
Part Number: [105891](#)
MODELS: ADP122

LP2 Stator
Part Number: [110930](#)
MODELS: ADP122

LP3 Stator
Part Number: [110929](#)
MODELS: ADP122

LP4 Stator
Part Number: [110927](#)
MODELS: ADP122

LP5 Stator
Part Number: [110925](#)
MODELS: ADP122

SHAFTS

Driving Shaft
Part Number: [111242](#)
MODELS: ADP122
Driven Shaft
Part Number: [111243](#)
MODELS: ADP122

LOBES

HP Lobe (short)
Part Number: [105149](#)
MODELS: ADP122

LP1 Lobe (medium)
Part Number: [329691](#)
MODELS: ADP122

LP2-3 Lobe (long)
Part Number: [329690](#)
MODELS: ADP122

OTHER COMPONENTS

Cool Plate
Part Number: [111232](#)
MODELS: ADP122

HP Support
Part Number: [105961](#)
MODELS: ADP122

LP Support
Part Number: [105148](#)
MODELS: ADP122

HP Bearing Clamping Flange
Part Number: [105157](#)
MODELS: ADP122

Deflector
Part Number: [105158](#)
MODELS: ADP122

Driving Impeller
Part Number: [060128](#)
MODELS: RSV602

Driven Impeller
Part Number: [060102](#)
MODELS: RSV602